



WATCH TOWER

BIBLE AND TRACT SOCIETY OF BRITAIN

THE RIDGEWAY LONDON NW7 1RN

TELEPHONE 020 8906 2211

TAK:TSC February 16, 2011

TO ALL BODIES OF ELDERS

Re: Halogen bulbs – Source of ignition

Dear Brothers:

Please find the attached pictures of halogen bulbs causing charring to the top of a literature cupboard door. This illustrates how hot halogen bulbs can be. As they are ceiling mounted, this is not normally a problem. However, the proximity of an opening door in this case resulted in a potential fire hazard.

We thought that it would be useful for you to have this information so that the chairman of the operating committee, or another elder assigned by the body of elders, can carefully check around any halogen bulbs. If you notice charring, take what safe action you can to deal with the problem, and if necessary, contact your Regional Building Committee.

Regional Building Committees have to be aware of the need to avoid designing in this potential, and the design of Kingdom Halls emanating from the branch office will be modified accordingly.

Please accept this expression of our warm Christian love and greetings.

Your brothers,

Watch Tower B. & J. Society
OF BRITAIN

Encl.: Pictures

cc: Travelling overseers
Regional Building Committees